

Aspect Suppressors

Armor Specialties LLC.
3234 Peter Mountain Rd.
Halifax PA 17032
717-827-3057

Cleaning procedure for the Aspect 22, Aspect 9 and Aspect 30 Series Suppressors.

Turning in a counter clockwise motion, remove the rear muzzle mount from the monolithic core and remove core assembly from the suppressor tube.

(When New or After heavy use, it may be necessary to use a wooden dowel or tool 14650 to lightly tap free)

Notice the orientation of the IC (Interior Core) covers. This will be important for reassembly if there is carbon build up. If assembling after cleaning replacing the covers on the core, orient them in the cover pockets. The covers are interchangeable from side to side so there is no wrong way to assemble the core before inserting in the tube. (Slight squeezing pressure may need to be applied on the covers to insert in the tube.)

Screw the muzzle device back into the core (Finger tight) and the suppressor is ready for use. (Over tightening when hot will make later disassembly more difficult).

Make sure the suppressor is properly tightened and installed on firearm before use.

It is recommended to place a coating of anti-seize on the core threads for easy removal.

Depending on your model, your new suppressor is made of stainless steel or Titanium.

Cleaning can be accomplished by chemical bath with a stiff bristle brush or abrasive sand blasting. Do **NOT** sand blast the Cerakote finish

WARNINGS

Every effort has been made to make this product a safe to use as possible but stainless steel is very hard and can hold a knife-like edge after aggressive cleaning It is advisable to wear leather gloves while cleaning your new suppressor

Modification Warning

Any modification to the suppressor by the end user or any third party will void the warranty

Liability Warning

Armor Specialties LLC does not assume liability for personal injury or property damage from the use or misuse of its products. It is the user's responsibility to implement the proper use of this product.

Warranty

Armor Specialties LLC offers a 3-year warranty and will repair or replace, any suppressor manufactured by Armor Specialties LLC. This warranty does not cover damage to the sound suppressor and/or host firearm resulting in whole or in part from criminal or negligent use, improper or careless handling, modifications, defective, improper hand loaded or reloaded ammunition or neglect. This warranty does not cover damage due to improper installation of the suppressor or an improperly threaded barrel. Any repairs not covered by this warranty will be charged to the owner.

Aspect Suppressors

Armor Specialties LLC.
3234 Peter Mountain Rd.
Halifax PA 17032
717-827-3057

Thread Guide ½ x 28 TPI

